



# Model ST-3602

## AC / DC Clamp Meters

### Features

- 3½ digit LCD with maximum reading of 1999.
- Over range indication : "1" is displayed on highest digit.
- Low battery indication: "B" sign appears on the display.
- Response time: approx. 1 second.
- Data hold: for all ranges

### Specifications

|                      |                                                               |
|----------------------|---------------------------------------------------------------|
| DC V:                | 200 / 1000V $\pm(1\%rdg+2dgt)$                                |
| DC A:                | 200 / 1500A $\pm(2\%rdg+4dgt)$                                |
| AC V:                | 200 / 750V $\pm(1.5\%rdg+2dgt)$ (40Hz-1kHz)                   |
| AC A:                | 200 / 1500A $\pm(2.0\%rdg+4dgt)$ (40Hz-1kHz)                  |
| $\Omega$ :           | 200 / 1500 $\Omega$ $\pm(1.5\%rdg+2dgt)$                      |
| Diode check:         | 0-1500mV $\pm(1.5\%rdg+2dgt)$                                 |
| Buzzer:              | Resistance is less than 100 $\Omega$                          |
| Current consumption: | Approx. 10mA                                                  |
| Conductor size:      | 55mm Max.                                                     |
| Operating:Temp.:     | 0°C ~ 40°C                                                    |
| Humidity:            | 85% R.H. Max                                                  |
| Power source:        | 9V(6F22) $\times$ 1                                           |
| Dimensions:          | 45(L) $\times$ 70(W) $\times$ 41.7(D)mm                       |
| Weight::             | Approx. 480g (battery Included)                               |
| Accessories:         | Instruction manual,<br>Test leads,<br>Soft pouch,<br>Battery. |

